

### **Technical Data Sheet**



01-12-2017

# Fix-Rite Farm & Ranch Exterior Alkyd Paint Low Luster - F613 Series

#### **Product Description**

Fix-Rite Farm & Ranch Exterior Alkyd Paint is designed to provide long lasting protection, at an economical price. Excellent for use on either wood or metal surfaces. It covers well, has good adhesion and spreads further than other more expensive paints. Its dried paint film is non-toxic to farm livestock.

#### **Recommended Use**

For use on wood or metal.

#### **General Surface Preparation**

Surfaces must be clean and free of surface contaminants. On previously painted surfaces, remove all loose or scaly paint by sanding or scraping so that all remaining paint is tightly adhered to the surface. Fill all of the holes and joints around windows, doors, trim, clapboards and other openings appropriately with exterior Spackle or caulking compound. Spot prime on all bare spots or badly eroded areas with CalPro Latex or Oil Primer.

Rusty metal must be abraded to remove scaling rust.

Mildewed areas should be cleaned with an EPA registered mildew solution. For protection use rubber gloves and safety goggles. Rinse with clean water and allow to dry before painting. In areas of excessive chalk, salt or dust, areas should be cleaned with pressure or scrubbed, then rinsed clean.

#### **Application**

FARM & RANCH PAINT is designed to be applied with a good quality paint applicator. Spot prime bare areas. Apply one or two coats to a properly prepared surface. Allow a minimum of 24 hours between coats. Spread paint evenly and thoroughly brush out. Do not over apply. Too heavy of a coat will result in sagging and drying problems. Avoid applying paint in direct sunlight.

#### Clean up

Clean tools and equipment with mineral spirits or turpentine. Do not use water on natural bristle or china bristle brushes.

#### **Architectural Specifications**

Ferrous Metal - Un-primed:

1 coat Rust Inhibiting Metal Primer

1 or 2 coats FixAll Fix Rite Farm and Ranch Alkyd Low Luster F613XX

New Wood, Clapboards, Shingles, Shakes, Trim:

1 Coat California CalPro Exterior Oil Primer 23100 or Calpro 100% Acrylic Latex Primer 46100

1 or 2 coats FixAll Fix Rite Farm and Ranch Alkyd Low Luster F613XX

New Masonry or Cement

Masonry Block, Porous Concrete:

1 or 2 coats FixAll Fix Rite Farm and Ranch Alkyd Low Luster F613XX

Wood-Repaint:

1 or 2 coats FixAll Fix Rite Farm and Ranch Alkyd Low Luster F613XX

#### **Precautions**

For exterior use only. Not for use on floors or decks. Nighttime dew settling on wet paint film will slow drying.

#### **Environmental Health and Safety Information**



## **Technical Data Sheet**



01-12-2017

Fix-Rite Farm & Ranch Exterior Alkyd Paint Low Luster - F613 Series



### **Technical Data Sheet**



01-12-2017

# Fix-Rite Farm & Ranch Exterior Alkyd Paint Low Luster - F613 Series

\*Depending upon color choice, non zero VOC colorant added to this product may significantly increase VOC levels.

WARNING: This product contains a chemical known to the State of California to cause cancer, birth defects or other reproductive harm.

Lead Warning ! - If you scrape, sand or remove old paint from any surface, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Carefully clean up with a wet mop or HEPA vacuum. Before you start, find out how to protect yourself and your family by contacting the U.S. EPA/Lead Information Hotline at 1-800-424-LEAD (5323) or log on to www.epa.gov/lead.

Always use any paint product with proper ventilation. Provide general dilution or local exhaust ventilation in volume and pattern to keep the air contaminant concentration below the applicable exposure limit (OSHA PEL) of the components being used. This information is listed on the appropriate Material Safety Data Sheets. All application areas should be ventilated in accordance with applicable OSHA regulations, contact your local office for specific information.

In an enclosed area and as required, always wear an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and after application of any coating unless air monitoring demonstrates that vapor/mist levels are below applicable limits. Follow respirator manufacturer's directions for respirator use.

CAUTION! Combustible Liquid: Keep away from heat and flame. Close container after each use. Use only with adequate ventilation. Wash thoroughly after handling. In case of spillage, absorb with inert material and dispose of in accordance with applicable regulations. KEEP OUT OF REACH OF CHILDREN.

USE COMPLETELY OR DISPOSE OF PROPERLY: Dispose of in accordance with applicable Federal, State and Local regulations. Under the Resource Conservation and Recovery Act (RCRA) regulations, it is the responsibility of the product user to determine, at the time of disposal, whether a material should be classified as a hazardous waste. For recycling guidance of any unused amount, contact your local or provincial organization of recovery, recycling and disposal for regulations.

Place the rags in an empty metal container that has a tight metal lid such as a paint or stain can. Fill the container with water until the rags are submerged; Fill Place the metal lid tightly over the water soaked formerly combustible rags. Place lid tightly on container. Coontact local municipal offices for disposal directions. Never dump solvent down any household or external drains or in any open water.

		п		
M			Δ	C
1.4	U	u		₽.

Technical Data				
Product Type	Industrial			
Exposure	Exterior			
Specular Gloss	8° ± 5			
Volume Solids	28% ± 2			
Weight Solids	44% ± 2			
Vehicle Solids				
Pigment				
Wet Film Thickness	3.5 - 7.0 mils			
Dry Film Thickness	1.0 - 2.0 mils			
Viscosity @ 77 °F				
Max VOC	450 g/l			
Flash Point ° F	Combustible			
Thinner	Mineral Spirits			
Clean - up	Mineral Spirits			
Surface Spread Rate				
Smooth	300-350 s.f./gal.			
Porous	250-300 s.f./gal.			
(Spray Application is 50% of above)				
Drying Times				
To Touch	16 hours			
To Handle	24 hours			
To Recoat	24 hours			
To Wash	7 days			
(@ 70 - 77 °F, 50% R.H)				
Surface Temperature At Application				
Maximum: Over 50°F	Maximum: Under 90°F			
Storage Temperature				
Store Between Over 35°F to Under 90°F				
Tools & Equipments				
Brush	Natural Bristle			
Roller	3/8" Nap Synthetic or Natural			
Airless Spray	.017 to .019 Tip			
Available Package Sizes				
5 Gallon	Gallon			
(Weight Per Gallon:9.8 lbs. ± .5 lb)				
Available Colors and Bases				

Available in 2 stock colors